

**ILLINOIS ENVIRONMENTAL PROTECTION AGENCY
MEMORANDUM**

DATE: 13 October 2010
TO: Bureau of Land File
FROM: Michelle Cozadd, BOL/FOS Collinsville Region
SUBJECT: LPC #1198010003 – Madison County
Hartford/Chemetco
FOS File

On September 24, 2010, I conducted a site visit at Chemetco, Inc. The purpose of the visit was to evaluate the screening operations in the Fines Building.


Fines Building

The screening equipment is shown in the attached photos #002 and #003. The broken concrete, damaged dimensional lumber, and other miscellaneous wastes that resulted from the screening were segregated in a separate pile inside the Fines Building. The material will be profiled for proper disposal off-site. The scrubber sludge dust was placed in the stockpile of metal bearing materials for potential reclamation at a later date. The scrubber sludge dust is shown in the attached photo #004. It appeared that no material or wastes from the screening operation were removed from the Fines Building at the time of this site visit.

cc: Regional File
cc: Erin Rednour
cc: Michelle Kerr – US EPA



SITE SKETCH



September 24, 2010 Inspection
Direction of Photo →
Photo Locations Approximate
Not to Scale



DIGITAL PHOTOGRAPHS



Date: 24 September 2010
Time: 10:20 am
Direction: W
Photo by: M. Cozadd
Exposure #: 001
Comments: Segregated broken concrete, damaged dimensional lumber, and other miscellaneous wastes from screening operations in Fines Building.



Date: 24 September 2010
Time: 10:20 am
Direction: NW
Photo by: M. Cozadd
Exposure #: 002
Comments: Screener in Fines Building.

File Names: 1198010003~09242010-[Exp. #].jpg



DIGITAL PHOTOGRAPHS



Date: 24 September 2010
Time: 10:20 am
Direction: W
Photo by: M. Cozadd
Exposure #: 003
Comments: Screener in fines building and material staged for screening to the right of equipment.



Date: 24 September 2010
Time: 10:20 am
Direction: NW
Photo by: M. Cozadd
Exposure #: 004
Comments: Screened material adjacent to northeastern wall of Fines Building.

File Names: 1198010003~09242010-[Exp. #].jpg



DIGITAL PHOTOGRAPH



Date: 24 September 2010
Time: 10:23 am
Direction: W
Photo by: M. Cozadd
Exposure #: 005
Comments: Segregated broken concrete, damaged dimensional lumber, and other miscellaneous wastes from screening operations in Fines Building.

NO PHOTO